CALIBRATING A THERMOMETER

1. Fill a medium-sized glass with ice and add cold water

2. Place metal-stemmed thermometer in ice water

3. Wait three minutes, stirring occasionally

4. After three minutes, thermometer should read 32°F

5. If it does not read 32°F, follow instructions below

To correct an inaccurate thermometer:

1. Leave thermometer in ice water; add ice if necessary

2. Using pliers or a wrench, turn the adjustable nut on the thermometer until the needle reads 32°F

3. Wait three minutes, stirring occasionally

4. After three minutes, thermometer should read 32°F (if it does not read 32°F, repeat the steps listed above)

CALIBRATE THERMOMETERS FREQUENTLY!